

Situation / History

- The town pool at Ballantine has one or two seasons of operations remaining before requiring major structural repairs.
- These pool repairs would require significant upgrades to the pool house as well, to bring the entire facility up to state building code as well as ADA compliance.
- While investigating the best course of action, the Edgewood Sports Complex in nearby Middlebury became available to purchase.
- The First Selectman has created an Ad Hoc Task Force to weigh the repair/replacement of Ballantine against the purchase of Edgewood as a new Town Pool, <u>beginning in 2021.</u>



Clarification: Town Pool

BALLANTINE WILL BE THE TOWN POOL IN 2020

EDGEWOOD, IF APPROVED AND PURCHASED, WOULD BE THE TOWN POOL IN <u>2021</u>



Decision Process

	AD HOC TASK FORCE	BOARD OF FINANCE	BOARD OF SELECTMEN
TASK	Is Edgewood an appropriate option to replace the current Town pool, and does the financial impact justify the purchase?	Decide whether to include the Edgewood purchase in the budget.	Determine the feasibility of a referendum and vote to authorize the purchase.
KEY DATES	April 16 — Submit Final Recommendation	April 20 — Joint meeting of BoF and BoS	July — Referendum if possible

Purpose of the Ad Hoc Task Force

First Selectman Jeff Manville tasked the Ad Hoc Committee to report back on the following:

- Is this purchase an appropriate option to replace the current Town pool?
- Does the financial impact justify the purchase?
- Recommend any engineering studies and inspections as to determine the condition of the Edgewood facility.
- Suggest any additional actions as necessary to achieve thorough due diligence.

TASK FORCE MEMBERS

George Bertram

Board of Selectman

Dan Colton

Finance Director

Charlie Rosa

Parks & Rec Commissioner

Tom Connor

Board of Finance

Tom Marks

Strategic Plan Commission

The Task Force worked closely with: **Jeff Manville, John Michaels** (BoF Chair) and **Hugh Sullivan** (architect)



Top 5 Edgewood Considerations



- 1. Deterioration of Ballantine
- 2. Premium Facilities at Edgewood
- 3. Populations Served
- 4. No Tax Increase or Bonding
- 5. Impact of Not Purchasing Edgewood



Deterioration of Ballantine Pool

Several factors have driven the discussion about the future of Ballantine pool:

- Ballantine pool is 50 years old and has one or two seasons remaining.
- Concrete and steel support deterioration requires significant reconstruction.
- Security concerns with access control.
- Inadequate parking (62 spaces).
- ADA requirements include working lift chairs (currently out of service) or a slopedentry/ramp.





Necessary Upgrades Of The Bath House

Any work done to the pool would require bringing the bath house up to code, including:

- Full ADA accessibility and compliance.
- Recalculation of plumbing features based on "assembly space" of pool, decking and building.
- Expansion of footprint from 1,640 sq. ft. to approximately 3000 sq. ft.
- Larger septic system.
- More van accessible handicap spots.







Cost Analysis to Replace Ballantine Pool

Report from Bennett Sullivan Associates Inc. based on analysis expert estimates:

Scott Pools · J&J Pools · Weston & Sampson Drakeley Pools · Greater Waterbury YMCA

Pool Replacement (Pool, Decking, Electric, Lighting)	\$2,529,000
Renovations to Bath House for ADA (Expand to 3000 SF)	\$825,000
Site Work (Septic, Well, Parking, Landscaping)	\$325,000
TOTAL	\$3,729,000



Analysis includes \$250k of contingency

Uncertainty in Cost Analysis

Based on Present Day Costs

Building costs rise over time; the most inexpensive time to build is today.

Based on Present Day Code

Code book expands over time, it's impossible to account for future requirements.

Cost Variance

We received a wide variance of estimates on the pool cost. We have confidence in the Sullivan analysis, especially the pool house, but the range suggests uncertainty.

Loss of Season

Depending on when the project begins, and the agreed timeline, the Town may be without a pool for one or two seasons.





Premium Pool Facility at Edgewood

	Olilili	12 Swimming	Parking		
	Pool Area SF	Weeks	Spaces	Decking SF	Pool House SF
EDGEWOOD	4,914+	18	159	14,250*	5,312
BALLANTINE	4,604	14	62	6,400	1,640

[†] Edgewood has six 25-yard swim lanes Ballantine has six 25-meter swim lanes



^{*} Includes adjacent patio outside pool fencing measuring 1800 square feet

Premium Pool Facility at Edgewood

					E
	Lighting	Heated	H2O Feature	Zero Entry	ADA Comp.
EDGEWOOD	X	X	X	X	X
BALLANTINE	*				

^{*} Lighting at Ballantine is non-functioning and not code compliant. Will need to be redone.



Additional Facilities Include

- 6 USTA-Grade Tennis Courts
- 2 Paddle Tennis Courts
- Regulation Basketball Court
- 3,500 Sq. Ft. Play Scape
- Beach Volleyball Court
- Commercial Kitchen w/ Liquor License
- 800 Sq. Ft. Gym Space with Equipment





Southbury Population Served



Summer Swim Families

A larger, new swimming pool Lap swimming for adults and triathletes



Senior Swimmers

Zero entry pool and working lifts



Sharks Swim Team

A 6-lane, 25 yard pool for competitions



Southbury Population Served



Parks and Rec Summer Camp

Camp currently uses Ballantine for after camp and buses to the pool. Edgewood would eliminate busing from Long Meadow School.



Pomperaug High School Tennis Team

Eliminates a \$1mm court reconstruction at High School



Recreational Tennis and Pickleball

Pickleball is a fast growing sport, especially with senior population



Southbury Population Served



Beginner Swim Lessons
Learning how to swim is a critical skill



Recreational Basketball

Community House basketball courts are at capacity on nice days



Paddle Tennis Players

Edgewood features the only Paddle Tennis courts in the surrounding towns of Middlebury, Woodbury, Newtown, Naugatuck or Waterbury





Financial Highlights

No Tax Increase or Bonding Required

Purchase will be funded with cash reserves and maintenance reserves.

Self-Sustaining Operating Model

Edgewood would be self-sustaining operation vs. a \$90k/annual deficit at Ballantine.

Long Term Maintenance

Pro forma includes allocation of a revenue fund for long term maintenance and repair.

Nominal Fee Increase

Town pool family fees will increase nominally, from \$320 to a target of \$350.




Financial Impact Analysis Overview

Town of Southbury

Ballantine and Projected Edgewood Revenues and Expenditures

	Current Ballantine	Proposed Edgewood	
Total Revenues:			
Southbury Residents Non-Residents Tennis & Other	\$ 65,764 6,182	\$ 124,460 128,000	
Total Revenue	\$ 71,946	\$ 312,710	
Expenditures:			
Labor	124,415	95,371	
Operating	19,634	82,495	
Tennis	-	5,508	
Maintenance	17,940	44,791	
Sewer Fees	-	18,340	
Middlebury Property Taxes	-	35,435	
Total Expenditures***	\$ 161,990	\$ 281,939	
Excess Revenue Over (Under) Expenditures	\$ (90,044)	\$ 30,771 *	



^{***} Based on 2019 actual expenditures





Impact of Not Purchasing Edgewood

If we were to pass on the Edgewood property, the town should be aware of the following considerations:

- Will another municipality purchase the property? We have been told another municipality that borders Middlebury is interested if the property becomes available.
- Will the new buyer be sensitive to our elementary school across the street? Currently the site is used as over-flow parking. Will a new owner be as accommodating?
- Can we find an alternative site for the PHS tennis teams?
 Court replacement estimate at PHS is \$1mm.



Pomperaug High School Tennis Courts



The tennis courts at Pomperaug High School are no longer in playable condition. The cost to repair the courts is estimated at \$1,000,000, of which Southbury would be responsible for 67%

The tennis teams have been playing at the Edgewood tennis courts for the past two seasons.

Region 15 will continue to "rent" the courts for the high school teams, to avoid a costly renovation. There are additional schools looking to rent the courts as well.




- 1. Why Invest in a Pool?
- 2. Why Invest in Property in Middlebury?
- 3. Why Not Repair Ballantine Pool?
- 4. What Will Happen to Ballantine Park?
- 5. What's In the Inspection Report?



Why Invest in a Pool?

Southbury's 6 Strategic Pillars



In 2018, the town of Southbury adopted its first Strategic Plan, as required by the Town Charter, for the purpose of setting the priorities for town governance and responsible and sustainable town growth.

A 2018 community survey indicates that 73.8% of residents place a high value on the recreational and cultural opportunities in Southbury and believe that Southbury should continue to invest in them.

Maintaining a public swimming pool would clearly be a priority based on the goals laid out in the Town's Strategic Plan.




Why Invest in a Pool?

- Having a pool was and is a source of pride for the Town, and separates us from neighboring towns that don't have a public pool.
- Learning to swim is an essential skill that prevents drownings. Having a first-rate Town pool with active programs facilitates this learning.
- Having a Town pool keeps Southbury desirable for young families.



Why Purchase Property in Middlebury?




Despite being located in Middlebury, the property is .6 miles over the town line, and would add 4 minutes, 22 sec to drive time*

*Based on an average of 30 randomly selected addresses. Locations listed in appendix.



Why Purchase Property in Middlebury?




Southbury has 4,996 single family homes

Approximately 65% of those residences are East of Main Street North / Route 6.



Why Purchase Property in Middlebury?



When the map is redistributed to the most populated areas, the drive time difference from Ballantine to Edgewood is under two minutes (1:58).

Newtown Community Center is a 4:35 longer drive on average.



Why Not Repair Ballantine Pool?

The Weston & Sampson engineering report project it would cost almost as much to repair the pool as to build a new one. This has been confirmed by several pool experts as well.



The Future of Ballantine Pool


The Task Force believes the town should remain committed to maintaining and enhancing Ballantine Park going forward, including the pool area. Therefore, the Task Force will be adding a condition to our recommendation that a new Task Force be formed to investigate how to best utilize Ballantine.

In the opinion of Hugh Sullivan, of Bennett Sullivan Associates, Inc., it would cost approximately \$50k to demolish and fill the pool at Ballantine.



Interpretation of Inspection Report

- Noted items were normal wear and tear.
- Seller has agreed to make repairs.
- A second inspection will be done to make sure repairs are made as required.
- A pool inspection will be performed when the pool is open.





Due Diligence Activities of the Task Force

- Site visit with Susie Jones, owner
- Site visit with Jim O'Rourke of Waterbury YMCA
- Meeting with Scott Pools, who built Ballantine
- Call with Paul Bette, State Building Inspector
- Building inspection and report
- Meeting with Newtown Community Center
- Financial impact analysis
- Review of courts with R.S. Site and Sports
- Discussion of engineering report with Weston & Sampson.
- Site visit with Bill Drakeley, whose firm built Edgewood pool
- Site visit with Mark Lancor of DYMAR, who did site engineering plans for Edgewood
- Meeting with Hugh Sullivan to discuss Ballantine compliance upgrades.






- 1. Maintain the Property in Peak Condition
- 2. Maintain Existing Programming
- 3. Keep Fees Affordable and Sustainable
- 4. Consider Options for Future Improvement




Future Development

Future development will be limited by wetlands on the property, however there is room for expansion in front of the clubhouse.





Possible Regional Community Center Location



Edgewood is positioned between several communities, which would making it an ideal location for a future regional community center, should we explore that option.

There are no other regional community centers with a five mile radius (shown in red).



Timeline of the Edgewood Purchase

April 1, 6, 13 The Edgewood Ad Hoc Task Force presents their initial

findings at informational town meetings.

April 16 Edgewood Ad Hoc Task Force formally submits report.

April 20 Joint meeting of Board of Selectmen and Board of Finance to

consider the Edgewood recommendation and vote.

June/July If possible, we will try to schedule an open house at Edgewood.

June 30 Final decision date for referendum if possible, for mid-July.

July 31 Option to purchase Edgewood Bath and Tennis Club expires.

120 Days Closing date is 120 days of the option date exercise.



Total Cost Summary of Edgewood

Purchase Price **\$2,000,000**

Closing Costs \$40,000

Court Resurfacing \$50,000

Contingency \$25,000

TOTAL COST \$2,115,000



Recommendation of the Task Force

The Edgewood Ad Hoc Task Force finds the Edgewood Bath and Tennis club to be a fiscally responsible and appropriate option to replace the current town pool at Ballantine. As such, we recommend exercising the Town's option to purchase with the following provisions:

- The town obtains a pool inspection report once the pool is open for the season.
- The Task Force remain in place to explore and recommend facility management options.
- The Task Force remain in place to explore community center options and improvements.
- A new Task Force be formed to explore future opportunities at Ballantine Park



Resources Available on Website

Please visit <u>southbury-ct.gov/edgewood</u> to access the following resources:

- Financial Impact Analysis
- Frequently Asked Questions
- DYMAR Engineering Site Plan for Edgewood
- Weston & Sampson Engineering Report on Ballantine Pool
- Inspection Report of Edgewood
- Bennett Sullivan Associates Inc. Analysis
- This Presentation



Questions?



Please submit questions on:

southbury-ct.org/edgewood

APPENDIX



- I. Lifetime of Edgewood Pool
- II. Summary of Estimates
- III. Drive Time Location Listing
- IV. Ballantine Pool House Reqs

Lifetime of Edgewood Pool

There is a general consensus among the pool contractors and experts we've spoken to that suggest the average lifetime of a commercial pool is 50 years, and a well built pool could last over 80 years.

In speaking with pool inspectors, two individuals were impressed when they learned that Drakeley built the Edgewood pool. One of them was quoted as saying that Drakeley pools are "rock solid."

William Drakeley is the first and only pool builder to sit as a Voting Member of the American Concrete Institute's (ACI) Committee 506 Shotcrete. Bill is also the former President of the American Shotcrete Association (ASA), the Chairman of the ASA's Pool and Recreational Shotcrete Committee, and Chairman of the ACI's Subcommittee 506-0H Pool Shotcrete.




Summary of Estimates

	Current Ballantine	COMPANY A	COMPANY B	COMPANY B 2nd Estimate	COMPANY C Renovation	COMPANY C Reconstruction	Bennett Sullivan Estimate	Edgewood
Pool Square Footage	4,590 sf	3,375 sf	4,159 sf	5,150 sf	4,500 sf	5,000 sf	5,000 sf	4,914 sf
Bath House Square Footage	1640 sf	3000 sf	3000 sf	3000 sf	3000 sf	3000 sf	3000 sf	5,000 sf
Pool Cost Estimate		\$1,130,500	\$1,380,000	\$1,490,000			\$2,529,000	
Sitework		\$375,000	\$375,000	\$375,000			\$375,000	
Bath House		\$825,000	\$825,000	\$825,000			\$825,000	
Total Cost		\$2,330,500	\$2,580,000	\$2,690,000	\$2,900,625	\$4,651,641	\$3,729,000	\$2,115,000



Drive Time Locations

Address Distance (mi) Time (min) Distance (mi) Time (min) Distance (mi) Time (min) 623 W Purchase Rd 7.7 16 12.2 19 4.5 3 770 Spruce Brook Rd 6.6 12 10.4 15 3.8 3 23 Little York Rd 6.3 14 10.9 20 4.6 6 84 Coughlin Dr 4.2 10 8.7 13 4.5 3 434 Heritage Village 4.1 9 6.7 14 2.6 5 355 Housatonic Trail 4.5 11 9.1 14 4.6 3 198 S Britain Rd 2.5 6 7 9 4.5 3 101 Royal Coach Ln 4.3 10 8.3 12 4 2 254 Bates Rock Rd 2.5 5 5.6 11 3.1 6 65 Shane Dr 5.1 12 9.1 13 4 1 77 Murphy Ln 3.2 <td< th=""><th></th><th colspan="2">Ballantine Pool</th><th>Edgewo</th><th colspan="2">Edgewood Pool</th><th colspan="2">Difference (E-B)</th></td<>		Ballantine Pool		Edgewo	Edgewood Pool		Difference (E-B)	
770 Spruce Brook Rd 23 Little York Rd 6.6 12 10.4 15 3.8 3 23 Little York Rd 6.3 14 10.9 20 4.6 6 84 Coughlin Dr 4.2 10 8.7 13 4.5 3 434 Heritage Village 4.1 9 6.7 14 2.6 5 3 355 Housatonic Trail 4.5 11 9.1 14 4.6 3 198 S Britain Rd 2.5 6 7 9 4.5 3 101 Royal Coach Ln 4.3 10 8.3 12 4 2 2 2 2 2 3 4 6 6 6 7 9 11 3.1 6 11 1 Noyal Hill Rd 4 9 7 9 11 3.9 2 4 6 6 6 6 6 7 9 9 4.5 3 6 6 6 7 9 4.5 3 6 6 6 7 9 9 4.5 3 6 6 6 7 9 9 4.5 3 6 6 6 7 9 9 4.5 3 6 6 6 7 9 9 4.5 3 6 6 6 7 9 9 4.5 3 6 6 6 7 9 9 4.5 3 6 6 6 7 9 4.5 3 6 6 6 7 9 9 4.5 3 6 6 6 7 9 9 4.5 3 6 6 6 7 9 9 4.5 3 6 6 6 6 7 9 9 11 3.1 6 6 11 70 Murphy Ln 3.1 6 6 6 6 6 6 6 7 9 9 11 3.9 2 2 3.6 6 6 6 6 6 6 6 7 9 9 11 3.9 2 2 3.6 6 6 6 6 6 7 9 9 11 3.9 2 2 3.6 6 6 6 6 7 9 12 3.6 6 6 6 6 7 9 13 3.6 6 6 6 6 7 9 2.3 3.6 6 6 6 6 7 9 2.3 3 3 4 2 2 2 2 3 3 3 4 2 2 3 4 2 2 3 4 2 3 4 2 3 4 3 4	Address	Distance (mi)	Time (min)	Distance (mi)	Time (min)	Distance (mi)	Time (min)	
23 Little York Rd 6.3 14 10.9 20 4.6 6 84 Coughlin Dr 4.2 10 8.7 13 4.5 3 434 Heritage Village 4.1 9 6.7 14 2.6 5 355 Housatonic Trail 4.5 11 9.1 14 4.6 3 198 S Britain Rd 2.5 6 7 9 4.5 3 101 Royal Coach Ln 4.3 10 8.3 12 4 2 254 Bates Rock Rd 2.5 5 5 5.6 11 3.1 6 11 Nod Hill Rd 4 9 7.9 11 3.9 2 460 Peter Rd 2.1 6 5.7 12 3.6 6 65 Shane Dr 5.1 12 9.1 13 4 1 77 Murphy Ln 3.2 8 5.2 10 2 2 507 Jeremy Swamp Rd 2.4 6 4.7 9 2.3 3 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 60 Hill Rd 5.1 11 9.7 14 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 50 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 10.7 16 4.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7	623 W Purchase Rd	7.7	16	12.2	19	4.5	3	
84 Coughlin Dr	770 Spruce Brook Rd	6.6	12	10.4	15	3.8	3	
434 Heritage Village 4.1 9 6.7 14 2.6 5 355 Housatonic Trail 4.5 11 9.1 14 4.6 3 198 S Britain Rd 2.5 6 7 9 4.5 3 101 Royal Coach Ln 4.3 10 8.3 12 4 2 254 Bates Rock Rd 2.5 5 5.6 11 3.1 6 11 Nod Hill Rd 4 9 7.9 11 3.9 2 460 Peter Rd 2.1 6 5.7 12 3.6 6 65 Shane Dr 5.1 12 9.1 13 4 1 77 Murphy Ln 3.2 8 5.2 10 2 2 507 Jeremy Swamp Rd 2.4 6 4.7 9 2.3 3 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0	23 Little York Rd	6.3	14	10.9	20	4.6	6	
355 Housatonic Trail 4.5 11 9.1 14 4.6 3 198 S Britain Rd 2.5 6 7 9 4.5 3 101 Royal Coach Ln 4.3 10 8.3 12 4 2 254 Bates Rock Rd 2.5 5 5 5.6 11 3.1 6 11 Nod Hill Rd 4 9 7.9 11 3.9 2 460 Peter Rd 2.1 6 5.7 12 3.6 6 65 Shane Dr 5.1 12 9.1 13 4 1 77 Murphy Ln 3.2 8 5.2 10 2 2 507 Jeremy Swamp Rd 2.4 6 4.7 9 2.3 3 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 283 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7		4.2	10	8.7	13	4.5		
198 S Britain Rd 2.5 6 7 9 4.5 3 101 Royal Coach Ln 4.3 10 8.3 12 4 2 254 Bates Rock Rd 2.5 5 5 5.6 11 3.1 6 11 Nod Hill Rd 4 9 7.9 11 3.9 2 460 Peter Rd 2.1 6 5.7 12 3.6 6 65 Shane Dr 5.1 12 9.1 13 4 1 77 Murphy Ln 3.2 8 5.2 10 2 2 507 Jeremy Swamp Rd 2.4 6 4.7 9 2.3 3 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 283 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7	434 Heritage Village	4.1	9	6.7	14	2.6	5	
101 Royal Coach Ln 4.3 10 8.3 12 4 2 254 Bates Rock Rd 2.5 5 5.6 11 3.1 6 11 Nod Hill Rd 4 9 7.9 11 3.9 2 460 Peter Rd 2.1 6 5.7 12 3.6 6 65 Shane Dr 5.1 12 9.1 13 4 1 77 Murphy Ln 3.2 8 5.2 10 2 2 507 Jeremy Swamp Rd 2.4 6 4.7 9 2.3 3 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 <td>355 Housatonic Trail</td> <td>4.5</td> <td>11</td> <td>9.1</td> <td>14</td> <td>4.6</td> <td>3</td>	355 Housatonic Trail	4.5	11	9.1	14	4.6	3	
254 Bates Rock Rd 11 Nod Hill Rd 4 9 7.9 11 3.9 2 460 Peter Rd 2.1 6 5.7 12 3.6 6 65 Shane Dr 5.1 12 9.1 13 4 1 77 Murphy Ln 3.2 8 5.2 10 2 2 507 Jeremy Swamp Rd 4.2 6 4.7 9 2.3 3 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 283 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 40 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 7 Totals 128 271 200 332 72 61	198 S Britain Rd	2.5	6	7	9	4.5		
11 Nod Hill Rd 4 9 7.9 11 3.9 2 460 Peter Rd 2.1 6 5.7 12 3.6 6 65 Shane Dr 5.1 12 9.1 13 4 1 77 Murphy Ln 3.2 8 5.2 10 2 2 507 Jeremy Swamp Rd 2.4 6 4.7 9 2.3 3 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5	101 Royal Coach Ln	4.3	10	8.3	12	4	2	
460 Peter Rd 2.1 6 5.7 12 3.6 6 65 Shane Dr 5.1 12 9.1 13 4 1 77 Murphy Ln 3.2 8 5.2 10 2 2 507 Jeremy Swamp Rd 2.4 6 4.7 9 2.3 3 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.	254 Bates Rock Rd	2.5	5	5.6	11	3.1	6	
65 Shane Dr 5.1 12 9.1 13 4 1 77 Murphy Ln 3.2 8 5.2 10 2 2 507 Jeremy Swamp Rd 2.4 6 4.7 9 2.3 3 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7	11 Nod Hill Rd	4	9	7.9	11	3.9	2	
77 Murphy Ln 3.2 8 5.2 10 2 2 2 507 Jeremy Swamp Rd 2.4 6 4.7 9 2.3 3 4 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 2 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 1 0 3 3 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7	460 Peter Rd	2.1	6	5.7	12	3.6	6	
507 Jeremy Swamp Rd 2.4 6 4.7 9 2.3 3 42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 <td>65 Shane Dr</td> <td>5.1</td> <td>12</td> <td>9.1</td> <td>13</td> <td>4</td> <td>1</td>	65 Shane Dr	5.1	12	9.1	13	4	1	
42 West Purchase Rd 7.5 13 11.1 17 3.6 4 201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7	77 Murphy Ln	3.2	8	5.2	10	2	2	
201 Beecher Dr 2.9 6 2.7 5 -0.2 -1 110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7	507 Jeremy Swamp Rd	2.4	6	4.7	9	2.3	3	
110 Beacon Hill Dr 4.2 9 3 6 -1.2 -3 282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7	42 West Purchase Rd	7.5	13	11.1	17	3.6	4	
282 Luther Dr 4.8 10 3.5 7 -1.3 -3 233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7	201 Beecher Dr	2.9	6	2.7	5	-0.2	-1	
233 Hulls Hill Rd 3.8 9 4.2 8 0.4 -1 516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7	110 Beacon Hill Dr	4.2	9	3	6	-1.2	-3	
516 Burr Rd 4.6 10 5.6 10 1 0 33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7	282 Luther Dr	4.8	10	3.5	7	-1.3	-3	
33 Old Oakwood Dr 4.6 9 1.6 3 -3 -6 266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7 Totals 128 271 200 332 72 61	233 Hulls Hill Rd	3.8	9	4.2	8	0.4	-1	
266 Hinman Ln 2.1 5 3.6 7 1.5 2 17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7 Totals 128 271 200 332 72 61	516 Burr Rd	4.6	10	5.6	10	1	0	
17 South Flat Hill Rd 6.1 13 10.7 16 4.6 3 482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7 Totals 128 271 200 332 72 61	33 Old Oakwood Dr	4.6	9	1.6	3	-3	-6	
482 Tepi Drive 9.9 19 13.5 22 3.6 3 30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7 Totals 128 271 200 332 72 61	266 Hinman Ln	2.1	5	3.6	7	1.5	2	
30 West Flat Hill Rd 5.1 11 9.7 14 4.6 3 255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7 Totals 128 271 200 332 72 61	17 South Flat Hill Rd	6.1	13	10.7	16	4.6	3	
255 flag swamp Rd 4.5 8 7.5 13 3 5 60 Turril Brook Dr 8.4 15 12.2 22 3.8 7 Totals 128 271 200 332 72 61	482 Tepi Drive	9.9	19	13.5	22	3.6	3	
60 Turril Brook Dr 8.4 15 12.2 22 3.8 7 Totals 128 271 200 332 72 61	30 West Flat Hill Rd	5.1	11	9.7	14	4.6	3	
Totals 128 271 200 332 72 61	255 flag swamp Rd	4.5	8	7.5	13	3	5	
		8.4	15	12.2	22	3.8	7	
	Totals	128	271	200	332	72	61	
	Average	9.14	19.36	14.31	23.71	5.17	4.36	





State Building Inspector Requirements

On March 9th, State Building Inspector Paul Bette told Mr. Bertram that "we would be required to provide 'accessibility' in the pool house if we redo the pool at Ballantine. He was quite clear about it. If we don't have handicapped accessibility in the pool house, then we'd have to provide it during any remodeling.

We may have to rebuild the pool house to obtain the State's approval. Based on a read of the Weston Samson report on Ballantine, the town complies with handicapped accessibility requirements by letting wheelchairs enter the pool deck through a staff/first aid entryway. I don't know if that is faithful compliance with ADA or not."



Weston & Sampson Report on Pool House

4.12 - Existing Challenges

Due to the layout and configuration of the locker rooms, patrons are not lead past the showers prior to entering onto the deck and can skip showering. When patrons skip the showers, oils and dirt are then brought into the pool. This results in the filtration system working harder to clean the pool, putting extra loads on the system.

Another challenge is that with the current configuration a handicap person in a wheel chair cannot easily make their way through the maze of the locker room. Many of the pathways are too narrow for a wheelchair to fit through or turn in. To avoid any complications the Town allows ADA access onto the pool deck through the staff/first aid entryway. The patron can then enter the locker room from the pool deck entrance. **Refer to Figure 12.**

The facility is also challenged with having to open after sunrise and close at sunset. There are outdoor lights at the facility but they no longer work. With no working outdoor lights the facility can only operate when the sun light allows, restricting the overall use and programs that could be offered.

