

SARA B. CRAWFORD HALL BUILDING FEASIBILITY STUDY
RFP 2026-015
ADDENDUM 1

- The site visit will meet at the Southbury Training School Physical Plant office, located at 1625 South Britain Road (map below). Attendees will be required to sign in and out at the office. The site visit will proceed to Crawford Hall following sign-in.
- Attendees are advised that proper attire and PPE are required for the site visit. This includes rugged closed-toed shoes and N95 respirators. Goggles and gloves are also recommended. N95s will be provided if not brought by attendees.

