

## **National Property Inspections**

Town of Southbury, 100 North Benson Road, Middlebury, CT, 06762

### Verification of repairs at 100 North Benson Road in Middlebury, CT

#### Repairs performed:

- Cracking in parking lot surface at front entryway sealed.
- Two new locking gate latches installed.
- Deteriorated basketball court surface repaired.
- All GFCI outlets and covers on tennis courts replaced.
- Light standards with damaged access covers repaired.
- Sliding track windows in three locations repaired.
- Minor leak at main water supplied repaired and corrosion cleared.
- Deteriorated rubber supply hoses for washing machine replaced.
- New condensate pump installed for HVAC unit #3
- Damaged shower heads in Women's and Men's locker rooms replaced, loose toilet repaired and leaking urinal flush valve repaired.
- Leak in office sink drain repaired.
- Latch for exercise room closet door repaired.

Inspection Date: 07/02/2020

Inspector: Giuseppe Volpato Inspector Phone: 203-871-7214 Email: volpato@npiinspect.com



## **National Property Inspections**

### Town of Southbury, 100 North Benson Road, Middlebury, CT, 06762



cracks have been sealed



cracks have been sealed



locking gate latch replaced



cracks have been sealed



locking gate latch replaced



court surface repaired

Inspection Date: 07/02/2020

5

Inspector: Giuseppe Volpato Inspector Phone: 203-871-7214 Email: volpato@npiinspect.com



# **National Property Inspections**

### Town of Southbury, 100 North Benson Road, Middlebury, CT, 06762

10

12



court surface repaired



GFCI outlet & cover repaired



GFCI outlet & cover repaired



GFCI outlet & cover repaired



GFCI outlet & cover repaired



lights standard repaired

Inspection Date: 07/02/2020

11

Inspector: Giuseppe Volpato Inspector Phone: 203-871-7214 Email: volpato@npiinspect.com HOI0000878



## **National Property Inspections**

### Town of Southbury, 100 North Benson Road, Middlebury, CT, 06762

13



lights standard repaired

15



sliding window repaired

17



corrosion & leak repaired

14




lights standard repaired

16



sliding window repaired

18



rubber supply line replaced

Inspection Date: 07/02/2020

Inspector: Giuseppe Volpato Inspector Phone: 203-871-7214 Email: volpato@npiinspect.com



# **National Property Inspections**

#### Town of Southbury, 100 North Benson Road, Middlebury, CT, 06762

19



condensate pump replaced

21



new shower head

23



leaking flush valve repaired

20



new shower head

22



loose toilet repaired

24



new shower head

Inspection Date: 07/02/2020

Inspector: Giuseppe Volpato Inspector Phone: 203-871-7214 Email: volpato@npiinspect.com



# **National Property Inspections**

#### Town of Southbury, 100 North Benson Road, Middlebury, CT, 06762

25



drain repair

26



door latch repaired

Inspection Date: 07/02/2020

Inspector: Giuseppe Volpato Inspector Phone: 203-871-7214 Email: volpato@npiinspect.com